





		ALFA-ŁAWA → 80 ↑ 48 ↘ 80		
x 4  (a)	x 10  (b)	x 4  (c)	x 16 (4x30)  (d)	
x 12  (e)	x 12  (f)	x 1  (g)		 30 min 

1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW

a - OZNACZENIE AKCESORIÓW

1




Diagram showing the base plate (A) being attached to the legs using screws (e).

2




Diagram showing the side panels (B, D) and (C, E) being attached to the base plate (A) using screws (e, f) and brackets (c). The panels are shown in two positions, labeled x 2.

3




Diagram showing the frame assembly. The side panels (B, C, D, E) are attached to the base plate (A) using screws (d) and brackets (a). The panels are shown in two positions, labeled (4x30).

4




Diagram showing the side panels (H) being attached to the frame using screws (d) and brackets (a). The panels are shown in two positions, labeled (4x30).

5




Diagram showing the final assembly of the table structure, with all panels (A, B, C, D, E, F, G, H) attached.

KA0318 - 14 / 0 / 1 / 0