











		ARES 3/1 → 81 + 128 + 29				
x 20  (a)	x 2  (b)	x 8  (c)	x 8  (d)	x 6  (e)	x 6  (f)	
x 3  (g)	x 2  (h)	x 4  (i)	x 2  (m)	x 12 (3,5x30)  (n)	  40 min	
x 58 (3,5x16)  (o)	x 18 (6,2x16)  (p)	x 2 (M4-12)  (r)	x 2  (s)	x 50  (t)	x 1  (u)	
x 3 kpl.  (i)	x 2 (214 mm)  (j)		x 4  (k)	x 2 (1162 mm)  (w)		

1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW

a - OZNACZENIE AKCESORIÓW


1

x 4

(a)

x 2

(c)



2

x 12


(a)

x 6

(c)




x 2

(h)

x 2

(j)

x 6
(3,5x16)

(o)


3

x 6

(f)


x 4

(a)




4

x 6




5

x 2




x 2




6

x 4







x 8




x 30




x 2





7



8



9



10

