




# CEZAR

→ 200 ↑ 198 ↘ 38






|                            |                          |                          |                          |              |              |                         |                          |
|----------------------------|--------------------------|--------------------------|--------------------------|--------------|--------------|-------------------------|--------------------------|
| x 26<br><br>a              | x 32<br><br>b            | x 32<br><br>c            | x 30<br><br>d            | x 7<br><br>e | x 7<br><br>f |                         |                          |
| x 4<br><br>g               | x 8<br><br>h             | x 5<br><br>j             | x 1 kpl.<br><br>k        | x 1<br><br>n | x 2<br><br>o | x 16<br>(4x20)<br><br>s | x 4<br>(3,5x30)<br><br>t |
| x 31<br>(3,5x16)<br><br>u  | x 24<br>(3x12)<br><br>w  | x 140<br><br>x           | x 1<br><br>y             | x 3<br><br>z | x 1<br><br>q | x 1<br><br>v            | x 1<br><br>w             |
| x 1 kpl. (300 mm)<br><br>i | x 1<br>(318 mm)<br><br>l | x 1<br>(338 mm)<br><br>m | x 1<br>(300 mm)<br><br>p | x 8<br><br>r | <br>120 min  |                         |                          |


1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW


a - OZNACZENIE AKCESORIÓW




4




5




6




7




8




9




10




11




12




13




14




15



16



17



18

