


x 16 	x 24 	x 24 	x 24 	x 4 	x 4 		
x 4 (400 mm - kpl.) 	x 2 	x 2 			40 min		
x 4 (Ø60 - 120 mm) 	x 4 (125 mm) 	x 4 					
x 12 (3,5x30) 	x 52 (3,5x16) 	x 50 	x 4 	x 6 (Ø6x18x2) 	x 4 (Ø60x7) 	x 4 	x 1

1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW

a - OZNACZENIE AKCESORIÓW



[illegible]

A diagram of a three-drawer unit. The unit is shown from a side-on perspective. The top drawer is labeled 'S1' and has a curved handle. The middle and bottom drawers are also labeled 'S1' and have curved handles. The unit is labeled 'A' on the left side, 'B' on the top right, 'C' on the top left, and 'm' on the right side. Arrows indicate the movement of the drawers: a double-headed arrow for the top drawer and single-headed arrows for the middle and bottom drawers.