










		ARES 2/1 → 81 + 93 + 29				
x 16 	x 2 	x 6 	x 6 	x 4 	x 4 	
x 2 	x 2 	x 3 	x 2 	x 12 (3,5x30) 	 	
x 44 (3,5x16) 	x 12 (6,2x16) 	x 2 (M4-12) 	x 2 	x 40 	x 1 	
x 2 kpl. 	x 2 (214 mm) 	x 4 	x 2 (810 mm) 			

1 - FAZY MONTAŻU


A - OZNACZENIE ELEMENTÓW

a - OZNACZENIE AKCESORIÓW

1

x 4


x 2

2


x 8


x 4


x 2


x 2



x 6
(3,5x16)

3

x 4



x 4

4

x 4


d



d

C

C



A


5

x 2

x 2

b

d



D

d

C

B

A

C

E

b

6

x 4

x 8
(3,5x16)

x 30





x 2
(810 mm)

k

o

t

w



k

o



k

k



o

k



7



8



9



10

